



Central California Chapter

MSW Isolation of Hazardous Energy

Required Attendance: PLW's performing high and medium risk IHE

Course Topics



- Isolation of Hazardous Energy Hazard Analysis
- Chevron Isolation Classifications
- Lock Out/Tag Out Requirements
- Equipment Isolation Procedures
- P&ID Basics
- Line Breaking



Schedule and Fees: Reservations are required!

Cancellation/No-show Policy:

All cancellation requests must be received 48 hours prior to class date to avoid cancellation fee (see fee schedule below). Any person who does not show up for the class they are enrolled in will be subject to the full class fee (members will be billed for students they enroll). Cancellations must be submitted in writing via e-mail training@abccentralcal.org or by calling 661-392-8729. No refunds or rescheduling for no-shows. **NO EXCEPTIONS.** Cancellation fees:

Cancellation fees:

\$50 cancellation fee will apply to all cancellations not received 48 hours before class date.

Class Time 7:30a-4:30p

5/7 & 5/8/19	6/4 & 6/5/19
7/15 & 7/16/19	8/19 & 8/20/19
9/11 & 9/12/19	10/17 & 10/18/19
11/6 & 11/7/19	12/4 & 12/5/19

\$350 for ABC Members

(ABC members may use available manhour training seats)

\$425 for Non-Members

(non-members must pre-pay for courses)

CALL 661-392-8729 to register

Training is held at:

ABC Central California Training Facility

19466 Flightpath Way
Bakersfield, CA 93308
(661) 392-8729



3 year wallet Card provided upon course completion.

MSW Comprehensive IHE Module includes classroom and hands-on training.



Visit our website at: www.abccentralcal.org